Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0103**

Resource Identification

Property Name(s): ..... House, 1220 Route 608 {Function/Location}
Property Date: 1910
Address(s): ..... 1220 Route 608 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior		
other	other		
Porch	Porch - 1-story, 3-bay	Wood	other
Roof	Roof - Gable	Asphalt	Roof - Shingle
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Single Dwelling
Est. Date of Construction: .... 1910 ca {VDHR Survey File} *Accessed?* .....
Primary Resource? ..... Yes *Number of Stories:* 1.0
Interior Plan Type: ..... *Threats to Resource:* .....
Description: Architecture Summary: Raised panel front door, vent in upper gable. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: Two room deep, central entrance End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic

Significance Statement: Typical early 20th century cottage in area.

Bibliographic Documentation

Ownership Information

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0103**

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: ..... 1990/7 /4
Organization or Person: ..... Willie Graham
CRM Event Notes or Comments: .....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-103
Negative no(s).

City/Town/Village/Hamlet: Windsor Vicinity
Street address or route number: 1220 Rte. 608
Historic name:
County: Isle of Wight
U.S.G.S. Quad: Windsor
Common name:

Present use: Dwelling
Original use: Dwelling
Building Style: Cottage
Building Date(s): ca. 1910

1. Construction Materials

- ☒ wood frame
- ☐ brick
  - bond: ☐ English ☐ Flemish ☐ ____-course American ☐ stretcher ☐ other ____
- ☐ stone
  - ☐ random rubble
  - ☐ coursed rubble
  - ☐ ashlar ☐ dressed ☐ rock-faced
- ☐ log:
  - ☐ squared ☐ unsquared
  - notching: ☐ V-notch ☐ saddle ☐ square ☐ half dovetail ☐ full dovetail ☐ diamond
- ☐ concrete block
- ☐ terra cotta
- ☐ steel frame
- ☐ other ____

2. Cladding Material

- ☒ weatherboard
- ☐ vertical siding
- ☐ board & batten
- ☐ shingle: ☐ wood ☐ asbestos ☐ asphalt
- ☐ bricktex
- ☐ other ____
- ☐ composition siding
- ☐ stucco
- ☐ aluminum or vinyl siding
- ☐ cast iron
- ☐ sheet metal
- ☐ enameled metal
- ☐ glass



3. Stories (number): 1
☐ low basement ☐ raised basement

4. Bays (number): front 3 side (church) ____
☐ symmetrical ☒ asymmetrical

5. Roof Type
- ☐ shed ☐ parapet?
- ☒ gable ☐ pediment? ☐ parapet? ☐ clipped end? ☐ cross gable? ☐ central front gable?
- ☐ hipped ☐ pyramidal?
- ☐ mansard
- ☐ false mansard
- ☐ gambrel
- ☐ flat ☐ parapet?
- ☐ roof not visible
- ☐ other ____

6. Roofing Material
- ☒ shingle
  - ☒ composition (asphalt, asbestos, etc.)
  - ☐ wood
- ☐ metal
  - ☐ standing seam
  - ☐ corrugated
  - ☐ pressed tin (simulated shingles)
- ☐ tile ☐ pantile ☐ flat ☐ glazed
- ☐ slate
- ☐ not visible

7. Dormers (number): front ____ side ____
☐ gable ☐ pediment?
☐ shed
☐ hipped

8. Primary Porch
style ____
stories 1
levels 1 bays 3
materials wood, asphalt shingle roof
description and decorative details
Square columns, shed roof.

9. General supplementary description and decoration: Raised-panel front door, six-over-six sash, unbeaded weatherboards, vent in upper gable.

10. Major additions and alterations:
Small addition to rear.

11. Outbuildings:

12. Landscape Features:

13. Significance: Typical early 20th-century cottage in area.

Surveyed by: Willie Graham Date: 7/4/90



FIGURE 9
Architectural Resources Identified During Survey